

CELL :- A128	CELL NAME:- Tensioner Body	MACHINE / STAGE :- Mazak/Machining	OPERATION :- Operation No. 10
--------------	----------------------------	------------------------------------	-------------------------------

KAIZEN THEME : To Prevent the defect at A128 Tensioner Body machining cell.

IDEA :- Provide limit interlock of tool wear offset.

WIDELY/DEEPLY:-

COUNTERMEASURE:- Provider limit interlock of tool wear offset ± 0.05 mm, now operator will give more than 0.1mm machine will give message Data over limit. & no change of ID Component damage & tool breakage.

BENCHMARK	10 Nos
TARGET	Zero
KAIZEN START	15.03.2016
KAIZEN FINISH	22.03.2016

PROBLEM / PRESENT STATUS :- $\varnothing 11.0$ ID Boar damage & tool get break due to Operator given 20 mm wear offset in machine while adjustment & No Limit & range Interlock of Tool wear offset in machine.

TEAM MEMBERS :-
N.S.Pujari .
Mr. Praveen

No Interlock System In Machine For Wear Offset Limit



BEFORE

Provided Interlock for Wear Offset Limit



AFTER

- BENEFITS :-**
- 1.Prevent In-house rejection.
 - 2.Prevent Tool Breakage.
 - 3.Prevent Machine Break Down .

KAIZEN SUSTENANCE

WHAT TO DO: ---
HOW TO DO: ---
FREQUENCY : Irreversible kaizen.

WHY - WHY ANALYSIS :-
Why1: $\varnothing 11.0$ ID Boar get damage.
Why2 : Operator given 20mm tool wear offset while adjustment.
Why 3:- No limit interlock of tool wear offset.

RESULT :-



COST INCURRED FOR MAKING KAIZEN

MATERIAL COST IN RS	LABOUR COST IN RS	TOTAL COST IN RS
----	---	----

ROOT CAUSE :- No limit interlock of tool wear offset.

SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT

REGISTRATION NO. & DATE: #1080, 31.03.16
REGISTERED BY :- N.S Pujari
MANAGER'S SIGN :- N.S.Pujari

SR. NO.	CELL	TARGET	RESPONSIBILITY	STATUS
1.	A157	31.03.16	M.E Dept.	Completed