		TPM CIRCLE NO :-		ΑCTIVITY	КК	QM	PM	JH	SHE	ОТРМ	DM	E & T			
AD IK		PM CIRCLE NAME :		LOSS NO./STEP									KAIZEN IDEA		
Plant : P14		DEPT :	IT	RESULT AREA	с	Q	Р	Р, С	S	M, D	Р, С	м	SHEET		
CELL :	TATA MPLS	CELL NAME :	TATA MPLS M/C STAGE :		N/W Cable			OPERATION:			N/W Cable Routing				
KAIZEN THEME :		KAIZEN IDEA :								BENCHMARK:					
To Improve The safety								TARGET:							
												02.02.2018			
												05.02.2018			
PROBLEM PRESENT STATUS :		COUNTERMEASURE:							KAIZEN FINISH:			05.02.2018			
		N/W Cable routed Thro' Wall to avoid Unsafe condition										P.Kumaravadivel			
Floor, unsafe while grass cutting using grass cutter M/C.									TEAM MEMBERS:		Sathish				
WHY-WHY ANALYSIS:		BEFORE			AFTER				BENEFITS:-						
Why1:- :- Possibility of N/W Failure					The state of the				Safe Working Condition						
						A CALL OF A CALL				KAIZEN SUSTAINANCE					
Why2:- Possibility of Accident during the										WHAT TO DO:					
Grass cutting		N/A							Cable Layed Thro' The Wall						
			^		-	-				TO DO:					
Why3:- Due to the N/W cable passing Thro'								-		king The	e Cable	on the	wall using		
the Floor ,It may struck the Cutter				12 A	1		-		Tie						
						FREQUENCY:									
									One Time						
ROOT CAUSE		RESULTS:				SCOPE & PLAN FOR HORIZONTAL									
							DEPLOYMENT								
N/W cable Passing Thro' the Grass Area					SR.	No	CE	LL/	_		_				
						PRODUC		TDC	RE	SP.	STATUS				
				jor,c											
REGISTRATION	P14/SHE/2018/027														
NO.:															
DATE:	10.03.2018		_	_											
	• · ·	Unsafe Cond		afe Working		_									
REGISTERED BY: Nigama		Condition			HC	HD SCOPE INFORMATION IN OTHER PLANT									
MANGERS SIGN:	Kumarvadivel	Before	e A	After	SR.	No	Pla	ant	W	HEN	WH	IOM	STATUS		
						-									