

CELL :- A247 L CELL NAME:- Lever MACHINE / STAGE :- SPM OPERATION :-Tapping

KAIZEN THEME -To Avoid A247 Lever Ø 6.3 hole shift.

IDEA :- Clamping strip & clamping pad gap done to be zero by modifying clamping pad .

WIDELY/DEEPLY:-

COUNTERMEASURE : Clamping strip & clamping pad gap done zero by modifying clamping pad .

PROBLEM / PRESENT STATUS -A247 Lever Ø 6.3 hole shift.



BEFORE



AFTER

BENCHMARK	18No.
TARGET	0 No.
KAIZEN START	08.01.2015
KAIZEN FINISH	18.01.2015

TEAM MEMBERS :-
Ganesh Padwalkar ,vijay walunj,
Nana Ugale, Nitin Sutar.


- BENEFITS :-**
1. Prevent Re-occurrence of Customer Complaint.
 2. Reduce COPQ.

KAIZEN SUSTENANCE

WHAT TO DO- Check Point added in Sustenance check sheet
HOW TO DO: By Audit
FREQUENCY : Alternate date

- WHY - WHY ANALYSIS :-**
- Why 1** - A247 Lever Ø 6.3 hole shift.
 - Why 2** - Part not clamp.
 - Why 3** - Clamp pad broken.
 - Why 4** - Excess load act on pad.
 - Why 5** - Gap between clamp strip & clamping pad.

RESULT :-



COST INCURRED FOR MAKING KAIZEN

MATERIAL COST	LABOUR COST	TOTAL COST
IN RS	IN RS	IN RS
-----	-----	-----

SCOPE & PLAN FOR HORIZONTAL DEPLOYMENT

SR. NO.	CELL	TARGET	RESPONSIBILITY	STATUS
---		-----	-----	-----

ROOT CAUSE- Gap between clamp strip & clamping pad

REGISTRATION NO. & DATE:- 08.01.2015

REGISTERED BY :- Ganesh Padwalkar

MANAGER'S SIGN :- Sunil kinkar